



Ottawa Lake  
Pit # 58-003  
7555 Whiteford Rd  
Ottawa Lake, MI 49267

11/06/2018

### 2100-AG LIME Limestone

Procedure	Sieve/Test	Average	Unit	Ag Lime
	3/8"	100.0	%	
	#4	99.9	%	
	#8	98.4	%	
	#10	96.3	%	
	#16	83.8	%	
	#30	60.5	%	
	#40	51.6	%	
	#50	43.6	%	
	#60	40.1	%	
	#100	34.6	%	
	#200	30.6	%	
	Wash Loss (#200/75um)	30.2	%	